



Local Worker Hiring Performance by PLA Covered Active Project as of April 15, 2016

| Total % Local Workers Key | | |
|---------------------------|-----------------------|----------------------|
| Meets or exceeds 30% goal | Within 3% of 30% goal | Not meeting 30% goal |

| Rank | Campus | Project Name | Prime Contractor | Project Number | Contract Number | Veterans | | | Local to College | | | | | Local to District | | | | | | |
|------|------------|--|-----------------------------------|---|-----------------|------------------------------|---------------------------|---------------------------|------------------|---------------|----------------------------|------------|------------------------|-------------------|--------------|---------------|----------------------------|------------|------------------------|-----------------|
| | | | | | | Total # of Workers on Campus | Total # of Local Veterans | Total % of Local Veterans | # of Workers | # of Veterans | # of Disadvantaged Workers | Veterans % | Disadvantaged Worker % | Local Worker % | # of Workers | # of Veterans | # of Disadvantaged Workers | Veterans % | Disadvantaged Worker % | Local Workers % |
| 1 | District | Corporate Center | Rosendin Electric | 40J.5192.05 | 33946 | 42 | 0 | 0 | 10 | 0 | 0 | 0% | 0% | 24% | 26 | 0 | 0 | 0% | 0% | 62% |
| 2 | Mission | Campus Modernization - Ph I | Masters Contracting, Inc. | 34M.5419.03 | 32529 | 328 | 0 | 0 | 48 | 0 | 2 | 0% | 1% | 15% | 149 | 0 | 13 | 0% | 4% | 45% |
| 3 | City | RWGPL Red Line Pedestrian Corridor (DOB) | Masters Contracting, Inc. | 11C.6173.05.03 | 33850 | 73 | 0 | 0 | 3 | 0 | 0 | 0% | 0% | 4% | 32 | 0 | 2 | 0% | 3% | 44% |
| 4 | Mission | Campus Modernization - Ph II | Masters Contracting, Inc. | 34M.5420.03 | 32879 | 184 | 0 | 0 | 22 | 0 | 1 | 0% | 1% | 12% | 80 | 0 | 3 | 0% | 2% | 43% |
| 5 | Pierce | Stadium ADA Improvements* | Balfour Beatty Construction | 35P.5537.03 | 33864 | 301 | 0 | 0 | 14 | 0 | 0 | 0% | 0% | 5% | 127 | 0 | 16 | 0% | 5% | 42% |
| 6 | Harbor | S.A.I.L.S | Bernard Brothers | 33H.5350.02.01, 33H.5350.02.02, 33H.5350.02.03, 33H.5350.02.07 | 33064 | 491 | 0 | 0 | 33 | 0 | 10 | 0% | 2% | 7% | 202 | 0 | 20 | 0% | 4% | 41% |
| 7 | Pierce | Phase 1A and 1B | Balfour Beatty Construction | 35P.5544.03.04 | 33859 | 394 | 0 | 0 | 22 | 0 | 0 | 0% | 0% | 6% | 163 | 0 | 20 | 0% | 5% | 41% |
| 8 | City | Clausen Hall Mod* | Sage Associates, Inc. | 31C.5107.03 | 33357 | 959 | 0 | 0 | 51 | 0 | 9 | 0% | 1% | 5% | 343 | 0 | 45 | 0% | 5% | 36% |
| 9 | Pierce | Campus Wide Telecommunications Upgrade | Balfour Beatty Construction | 35P.5544.03.04 | 33861 | 47 | 0 | 0 | 6 | 0 | 0 | 0% | 0% | 13% | 17 | 0 | 0 | 0% | 0% | 36% |
| 10 | Mission | Media Arts Center | Kemp Brothers | 34M.5405.02 (aka 04M.6405.02) | 32594 | 726 | 0 | 0 | 61 | 0 | 10 | 0% | 1% | 8% | 253 | 0 | 16 | 0% | 2% | 35% |
| 11 | Southwest | DB-2 Little Theater Upgrade, Cox Building Upgrade, Lecture Laboratory Building – Modernization, Campus-Wide Storm water Collection System, Fitness and Wellness Center and Northeast Quadrant Parking Structure project.** | Hensel Phelps Construction Co | 36S.5607.03.09,36S.5607.03.10,36S.5618.03.01,36S.5663.03.02,36S.5667.03,36S.5668.02 | 33063 | 2343 | 0 | 0 | 109 | 0 | 4 | 0% | 0% | 5% | 801 | 0 | 54 | 0% | 2% | 34% |
| 12 | City | Life Sciences & Chemistry Buildings Modernization and New Construction of Health, Fitness & PE Bldg.* | Woodcliff Corporation | 31C.5150.03/ 31C.5151.03/ 11C.7115.02 | 33149 | 831 | 0 | 0 | 35 | 0 | 5 | 0% | 1% | 4% | 285 | 0 | 33 | 0% | 4% | 34% |
| 13 | City | Student Services Center and Holmes Hall Modernization | Harper Construction Company Inc. | 11C.7134.05/31C.5134.02/31C.5134.05C/01C.6110.03/11C.7110.03/31C.5110.03 | 33741 | 947 | 0 | 0 | 32 | 0 | 11 | 0% | 1% | 3% | 315 | 0 | 11 | 0% | 1% | 33% |
| 14 | East | Science Career and Mathematics Building | Harper Construction Company Inc. | 32E.5222.02.03/32E.5222.02.04/32E.5222.02.05/32E.5222.02.06 | 33801 | 804 | 0 | 0 | 87 | 0 | 3 | 0% | 0% | 11% | 266 | 0 | 12 | 0% | 1% | 33% |
| 15 | Trade Tech | Construction Technology Building & East Parking Structure | Bernard Brothers | 37T.5720.02.01 / 37T.5714.02.02 | 33148 | 679 | 0 | 0 | 39 | 0 | 6 | 0% | 1% | 6% | 218 | 0 | 21 | 0% | 3% | 32% |
| 16 | Valley | Monarch Center & Parking Structure | McCarthy Building Company | 38V.5842.02/08V.684.02.02 | 33349 | 1593 | 0 | 0 | 55 | 0 | 0 | 0% | 0% | 3% | 483 | 0 | 7 | 0% | 0% | 30% |
| 17 | Valley | Athletic Training Facility (LLB) | Clark Construction | 38V.5837.02 | 33833 | 919 | 3 | 0% | 44 | 0 | 0 | 0% | 0% | 5% | 280 | 0 | 56 | 0% | 6% | 30% |
| 18 | East | Performing Arts Center | Knightcare, Inc. | 02E.6207.02 | 33885 | 10 | 0 | 0 | 0 | 0 | 0 | 0% | 0% | 0% | 3 | 0 | 0 | 0% | 0% | 30% |
| 19 | East | Student Success and Retention Center | Pinner Construction Company, Inc. | 32E.5234.02 | 32975 | 1653 | 0 | 0 | 198 | 0 | 8 | 0% | 0% | 12% | 481 | 0 | 20 | 0% | 1% | 29% |
| 20 | Valley | Community Workforce & Omega Center | Charles Pankow Builders | 38V.5836.02 | 33436 | 896 | 0 | 0 | 24 | 0 | 1 | 0% | 0% | 3% | 264 | 0 | 4 | 0% | 0% | 29% |

| | | | | | | | | | | | | | | | | | | | | |
|----|---------------|---|----------------------------------|--|-------|------|---|---|----|---|---|----|----|----|-----|---|----|----|----|-----|
| 21 | Valley | Multi-Purpose Community Ctr | Charles Pankow Builders | 38V.5839.02/08V.6837.02.01 | 33388 | 838 | 0 | 0 | 15 | 0 | 0 | 0% | 0% | 2% | 227 | 0 | 11 | 0% | 1% | 27% |
| 22 | Southwest | DB-1 Pump House Project | Harper Construction Company Inc. | 36S.5679.02.08 | 32881 | 695 | 0 | 0 | 52 | 0 | 1 | 0% | 0% | 7% | 189 | 0 | 1 | 0% | 0% | 27% |
| 23 | Mission | Campus Mod. - Ph 3 DSEO*** | Johnson Controls | 14M.7486.05 | 32252 | 59 | 0 | 0 | 2 | 0 | 0 | 0% | 0% | 3% | 16 | 0 | 0 | 0% | 0% | 27% |
| 24 | City | Physical Plant (M&O Building) & Tennis Courts | Charles Pankow Builders | 31C.5146.02/31C.5152.02 | 33648 | 508 | 0 | 0 | 7 | 0 | 0 | 0% | 0% | 1% | 131 | 0 | 1 | 0% | 0% | 26% |
| 25 | East | Campus Student Center and Book Store | Edge Construction, LLC | 32E.5231.02 | 33116 | 1109 | 0 | 0 | 98 | 0 | 4 | 0% | 0% | 9% | 280 | 0 | 8 | 0% | 1% | 25% |
| 26 | District Wide | Measurement & Demand Response (M&DR) | Climatec Building Technologies | 40I.5101.02.02, 40I.5201.02.02, 40I.5301.02.02, 40I.5401.02.02, 40I.5501.02.02, 40I.5701.02.02, 40I.5801.02.02, 40I.5901.02.02, 40I.5601.02.02 | 33803 | 30 | 0 | 0 | 0 | 0 | 0 | 0% | 0% | 0% | 6 | 0 | 0 | 0% | 0% | 20% |

| | | | | | | | | | | | | | | | | | | | | |
|----------------------------|--|--|--|--|--|-------|---|----|------|---|----|----|----|----|------|---|-----|----|----|-----|
| Project Grand Total | | | | | | 17459 | 3 | 0% | 1067 | 0 | 75 | 0% | 0% | 6% | 5637 | 0 | 374 | 0% | 2% | 32% |
|----------------------------|--|--|--|--|--|-------|---|----|------|---|----|----|----|----|------|---|-----|----|----|-----|

| | |
|-----|---|
| * | Project in punchlist (substantial completion) |
| ** | Commissioning (substantially complete) |
| *** | Project currently on hold |



LOCAL WORKER HIRING PERFORMANCE BY SUBCONTRACTOR
Valley - Athletic Training Facility
Clark Construction
Contract # 33833
Project # 38V.5837.02

| Project Summary | Total # of Workers | |
|------------------------|--------------------|------------|
| | 919 | |
| | Count | Percentage |
| District Local | 280 | 30% |
| District Disadvantaged | 56 | 6% |
| District Veteran | 0 | 0% |
| College Local | 44 | 5% |
| College Disadvantaged | 0 | 0% |
| College Veteran | 0 | 0% |
| Total Veterans | 3 | 0% |

| Company | Total # of Workers | # of Disadvantaged | # of College Local Workers | # of District Local Workers | District Disadvantaged % | College Local % | District Local % | Total # of Veterans | Veteran % of Total Workers | # of District Local Veterans | District Local Veterans % |
|--------------------------------------|--------------------|--------------------|----------------------------|-----------------------------|--------------------------|-----------------|------------------|---------------------|----------------------------|------------------------------|---------------------------|
| Advanced Cable Solutions | 16 | 0 | 1 | 8 | 0% | 6% | 50% | 0 | 0% | 0 | 0% |
| Advanced Equipment Corporation | 5 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Air Balance Co. | 5 | 0 | 0 | 1 | 0% | 0% | 20% | 1 | 20% | 0 | 0% |
| Alcorn Fence Company | 33 | 13 | 4 | 14 | 39% | 12% | 42% | 0 | 0% | 0 | 0% |
| Barney's Hole Digging Services, Inc. | 5 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Beyond the Turf, Inc. | 20 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Bielski Specialty Services, Inc. | 2 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Boer Backhoe, Inc. | 2 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Byrom-Davey, Inc. | 10 | 3 | 0 | 3 | 30% | 0% | 30% | 0 | 0% | 0 | 0% |
| Canyon Insulation, Inc. | 8 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Capital Door Service | 1 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Carey Sign Corporation | 1 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Centerline Concrete Cutting, Inc. | 3 | 0 | 1 | 1 | 0% | 33% | 33% | 0 | 0% | 0 | 0% |
| Circulating Air, Inc. | 22 | 0 | 2 | 7 | 0% | 9% | 32% | 0 | 0% | 0 | 0% |
| Clark Construction | 6 | 1 | 0 | 2 | 17% | 0% | 33% | 0 | 0% | 0 | 0% |
| Continental Marble & Tile Co. | 18 | 3 | 0 | 13 | 17% | 0% | 72% | 0 | 0% | 0 | 0% |
| Crane Rental Service | 3 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Crowner Sheet Metal Products, Inc. | 45 | 0 | 1 | 15 | 0% | 2% | 33% | 0 | 0% | 0 | 0% |
| DeYoung Power Systems, Inc. | 5 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| DM Ironworks | 5 | 0 | 2 | 2 | 0% | 40% | 40% | 0 | 0% | 0 | 0% |
| DSM Construction, Inc. | 10 | 0 | 0 | 3 | 0% | 0% | 30% | 0 | 0% | 0 | 0% |
| FBM GWBM, Inc. | 12 | 0 | 1 | 5 | 0% | 8% | 42% | 0 | 0% | 0 | 0% |
| Final Cleaning Solutions, Inc. | 11 | 7 | 0 | 10 | 64% | 0% | 91% | 0 | 0% | 0 | 0% |
| First Responder Fire Protection | 5 | 0 | 0 | 2 | 0% | 0% | 40% | 1 | 20% | 0 | 0% |
| Genesis Floor Covering, Inc. | 7 | 0 | 0 | 2 | 0% | 0% | 29% | 0 | 0% | 0 | 0% |
| GGG Demolition | 12 | 1 | 1 | 7 | 8% | 8% | 58% | 0 | 0% | 0 | 0% |

| | | | | | | | | | | | |
|--|----|----|----|----|-----|-----|------|----|----|---|----|
| Granitex Construction | 57 | 6 | 0 | 15 | 11% | 0% | 26% | 0 | 0% | 0 | 0% |
| GVCO Construction Inc. | 18 | 2 | 1 | 6 | 11% | 6% | 33% | 0 | 0% | 0 | 0% |
| GW Surfaces (sub to Stolo Cabinets) | 4 | 0 | 1 | 1 | 0% | 25% | 25% | 0 | 0% | 0 | 0% |
| Hill Crane Services | 2 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Howard Roofing Company, Inc. | 11 | 0 | 1 | 3 | 0% | 9% | 27% | 0 | 0% | 0 | 0% |
| ISR Painting & Wallcovering, Inc. | 11 | 0 | 0 | 3 | 0% | 0% | 27% | 0 | 0% | 0 | 0% |
| Karcher Interior Systems, Inc. | 5 | 0 | 0 | 1 | 0% | 0% | 20% | 0 | 0% | 0 | 0% |
| Lukkes Striping, Inc. | 7 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Martin Integrated Systems | 3 | 0 | 0 | 1 | 0% | 0% | 33% | 0 | 0% | 0 | 0% |
| Masonry Concepts, Inc. | 41 | 3 | 2 | 13 | 7% | 5% | 32% | 0 | 0% | 0 | 0% |
| Merli Concrete Pumping | 19 | 0 | 0 | 6 | 0% | 0% | 32% | 0 | 0% | 0 | 0% |
| Mike Russell Construction, Inc. | 17 | 0 | 0 | 1 | 0% | 0% | 6% | 0 | 0% | 0 | 0% |
| Mollenhauer Group Construction Survey Inc. | 8 | 0 | 0 | 1 | 0% | 0% | 13% | 0 | 0% | 0 | 0% |
| Murray Company | 26 | 0 | 1 | 6 | 0% | 4% | 23% | 0 | 0% | 0 | 0% |
| Optima Door & Frame, Inc. | 6 | 0 | 0 | 2 | 0% | 0% | 33% | 0 | 0% | 0 | 0% |
| Penhall Company | 10 | 0 | 0 | 5 | 0% | 0% | 50% | 0 | 0% | 0 | 0% |
| Pefrection Glass, Inc. | 19 | 0 | 0 | 3 | 0% | 0% | 16% | 0 | 0% | 0 | 0% |
| Performance Contracting, Inc. | 91 | 3 | 3 | 18 | 3% | 3% | 20% | 0 | 0% | 0 | 0% |
| Pierre Landscape | 44 | 11 | 10 | 24 | 25% | 23% | 55% | 0 | 0% | 0 | 0% |
| Post Earthworks Construction | 13 | 0 | 1 | 4 | 0% | 8% | 31% | 0 | 0% | 0 | 0% |
| Power Testing & Energization, Inc. | 2 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Proulx Contracting, Inc. | 1 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| RCB Specialties, Inc. | 3 | 0 | 0 | 3 | 0% | 0% | 100% | 0 | 0% | 0 | 0% |
| Rebar Engineering Inc. | 43 | 0 | 4 | 18 | 0% | 9% | 42% | 0 | 0% | 0 | 0% |
| Renteria Flooring Specialist | 4 | 0 | 0 | 3 | 0% | 0% | 75% | 0% | 0% | 0 | 0% |
| Richard A. Reed Backhoe Service, Inc. | 3 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Safe Scaffolding | 13 | 0 | 0 | 4 | 0% | 0% | 31% | 0 | 0% | 0 | 0% |
| Sheward & Sons & Sons | 6 | 0 | 0 | 0 | 0% | 0% | 0% | 0% | 0% | 0 | 0% |
| SME Industries, Inc. | 9 | 0 | 0 | 1 | 0% | 0% | 11% | 0 | 0% | 0 | 0% |
| Stolo Cabinets, Inc. | 7 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Sunbelt Controls, Inc. | 11 | 0 | 1 | 1 | 0% | 9% | 9% | 0 | 0% | 0 | 0% |
| T&M Manufacturing, Inc. | 27 | 0 | 2 | 8 | 0% | 7% | 30% | 0 | 0% | 0 | 0% |
| Taft Electric Company | 46 | 0 | 1 | 18 | 0% | 2% | 39% | 1 | 2% | 0 | 0% |
| The J.V Land Clearing Co. | 10 | 0 | 0 | 0 | 0% | 0% | 0% | 0 | 0% | 0 | 0% |
| Union Modular Construction, Inc. | 5 | 0 | 0 | 1 | 0% | 0% | 20% | 0 | 0% | 0 | 0% |
| Western Paving Contractors, Inc. | 29 | 0 | 0 | 9 | 0% | 0% | 31% | 0 | 0% | 0 | 0% |
| West Coast Netting, Inc. | 7 | 2 | 2 | 3 | 29% | 29% | 43% | 0 | 0% | 0 | 0% |
| West Coast Turf | 4 | 0 | 1 | 1 | 0% | 25% | 25% | 0 | 0% | 0 | 0% |
| Zolnay Insulation, Inc. | 5 | 1 | 0 | 2 | 20% | 0% | 40% | 0 | 0% | 0 | 0% |

| | | | | | | | | | | | |
|--------------------|------------|-----------|-----------|------------|-----------|-----------|------------|----------|-----------|----------|-----------|
| Grand Total | 919 | 56 | 44 | 280 | 6% | 5% | 30% | 3 | 0% | 0 | 0% |
|--------------------|------------|-----------|-----------|------------|-----------|-----------|------------|----------|-----------|----------|-----------|